



To reduce the risk of electric shock, fire, explosion, serious injury or death:
 Disconnect electric power to the machine(s) before servicing.
 Close shut-off valve to gas dryer(s) before servicing.
 Never start the machine(s) with any guards/panels removed.

Symptoms

Solutions

**Customer
Banging on
Machine**

- Level machine
- Clean coin drop
- Replace coin drop

**Coin Not
Falling**

- Level machine
- Clear coin jam
- Clean coin drop
- Replace coin drop

**Coin Not
Returning**

- Clean coin drop
- Replace coin drop

**Coin Not
Recognized
by Control**

- Clean opto coupler
- Check connections at control and drop(s)
- Replace opto coupler
- Replace coin drop

Coin Error

- Clean opto coupler
- Replace opto coupler
- Replace coin drop

Watch our product trainer demonstrate removing the coin drop for cleaning at <http://alsu.alliancels.net/Service-Videos/Huebsch>

