



Replacing the drive motor - stack tumble dryer



WARNING

To reduce the risk of electric shock, fire, explosion, serious injury or death:

Disconnect electric power to the machine(s) before servicing.

Close shut-off valve to gas dryer(s) before servicing.

Never start the machine(s) with any guards/panels removed.

Symptoms

Solutions

**Motor does
not start**

- Check power supply
- Close door panel
- Check door switch
- Replace drive motor

**Burner does
not ignite**

- Check external supply fuses
- Reset switch on control
- Test cabinet limit thermostat
- Test stove limit thermostats
- Check gas supply
- Check orifices
- Check for lint buildup
- Check make-up air
- Check fuse
- Open shut-off valve
- Connect ground wire
- Replace IEI control
- Replace drive motor

Watch our product trainer demonstrate replacing the drive motor at
<http://alsu.alliancels.net/Service-Videos/Huebsch>