



# Cleaning and Replacing the Lint Filter - Stack Tumble Dryer



**To reduce the risk of electric shock, fire, explosion, serious injury or death:**  
 Disconnect electric power to the machine(s) before servicing.  
 Close shut-off valve to gas dryer(s) before servicing.  
 Never start the machine(s) with any guards/panels removed.

## Symptoms

## Solutions

Long Dry Times

- Too large of load
- Clean/Replace lint filter

Ripped Filter

- Replace filter

Motor Overload Protector Cycles Repeatedly

- Too large of load
- Check voltage
- Check cylinder
- Check lint
- Clean/Replace lin filter

Burner Repeatedly Cycles Off on High Limit Thermostat

- Check exhaust requirements
- Check make-up air
- Clean/Replace lint filter
- Check exhaust system for excessive lint
- Check high limit thermostat
- Check lint panel door

Overheating

- Check heat source (i.e. gas, steam)
- Check make-up air
- Clean/Replace lint filter
- Check exhaust system for excessive lint
- Check thermistor

Watch our product trainer demonstrate cleaning and replacing the lint filter at <http://alsu.alliancels.net/Service-Videos/Huebsch>



October 2017  
10-17-366